



United States Environmental Protection Agency
Office of Criminal Enforcement, Forensics & Training
CHAIN OF CUSTODY RECORD

201404152



United States Environmental Protection Agency
Office of Criminal Enforcement, Forensics & Training
CHAIN OF CUSTODY RECORD

[CONTINUATION PAGE]

Item/Sample Number	Date / Time	Relinquished By	Received By	6. Purpose of Change of Custody	7. Remarks:
		Print Name & Organization:	Print Name & Organization:		
		Signature:	Signature:		
		Print Name & Organization:	Print Name & Organization:		
		Signature:	Signature:		
		Print Name & Organization	Print Name & Organization		
		Signature:	Signature:		
		Print Name & Organization:	Print Name & Organization:		
		Signature:	Signature:		

FINAL DISPOSITION ACTION

Release to Owner or Other:

Destroy:

Other (specify):

Authorized By:	Printed Name:	Signature:	Title & Organization:	Date:
FORM: OCEFT 7-01(b) (2/11)				

**United States Environmental Protection Agency
Office of Criminal Enforcement, Forensics and Training
RECEIPT**

RECEIVED FROM (b) (6), (b) (7)(C) Cleveland, MS		CASE NUMBER 0411-M210
PURPOSE Evidence		DATE 1-28-15
OFFICE GBRO		
ITEM NO.	ITEM DESCRIPTION	
1	Manilla envelope containing CD mailed to (b) (6), (b) (7)(C)	
2	Manilla envelope containing CD mailed to (b) (6), (b) (7)(C)	
3	Manilla envelope containing CD mailed to (b) (6), (b) (7)(C)	
4	Manilla envelope containing CD mailed to (b) (6), (b) (7)(C)	
5	6 pages of notes on chronology of events for Boyle-Skeen Water	
6	Case # B14-00000395, Synopsis for (b) (6), (b) (7)(C) SO	
7.	Bolivar SO Incident Report Copies - 2014060053, 201409006, 2014090042, 2014004152	
5	(b) (6), (b) (7)(C)	
WITNESS		DATE 1/28/15
DATE		

Synopsis

On Tuesday, July 30, 2014, I MBI Agent (b) (6), (b) (7)(C) met with (b) (6), (b) (7)(C) of the Boyle Water Association (BWA). The purpose of this meeting was to gather information of alleged vandalism to various the water lines in and around rural Bolivar County Mississippi. These water lines were owned and serviced by the BWA, which provide water to a large portion of rural Bolivar County. (b) (6), (b) (7)(C) advised me that there had been some damage cause to water supply line that was controlled by the Association. She would receive calls from residents stated that they had low water pressure. A service person would go out to investigate and would discover the damaged water lines near the complaint.

She stated that these incidents did not occur until after (b) (6), (b) (7)(C) was terminated from the company. (b) (6), (b) (7)(C) had been employed with the company as the overseer of the Water Association, Which she (b) (6), (b) (7)(C) was the (b) (6), (b) (7)(C) at the time. After (b) (6), (b) (7)(C) termination (b) (6), (b) (7)(C) assumed the responsibilities of management.

Since the termination a sequence of vandalism has occurred to main water lines that serviced smaller residential communities.

(b) (6), (b) (7)(C)

Several water mains have been bust, which lead to residents near the damaged water mains to experience extremely low water pressure. On frequent occasions, (b) (6), (b) (7)(C) was seen in close proximity of the damaged water mains.

On **Thursday, July 31, 2014**, late in the evening, I was contacted by (b) (6), (b) (7)(C) via Cell phone. The purpose of this call was to inform me that BSWA maintenance man (b) (6), (b) (7)(C) observed (b) (6), (b) (7)(C) in a black pickup truck parked near Shaw Skene Road and Litton Road.

On **Friday, August 1, 2014**, I was contacted by (b) (6), (b) (7)(C), who was advised that another damaged water main was discovered on Highway 448 West of Shaw at an abandon air stripe. This stripe was at one point used by local crop-duster pilots to provide service to local farmers.

After I arrived on the location, I observed (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) and (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) was working several feet to the north of the damage line to repair the leak. From my observation I notice that what appeared to be the white PVC pipe damage near the cut-off valve. The damage appeared to have been cause by someone striking it with object that was round in diameter. During the same time, I, agent (b) (6), (b) (7)(C) observe a black pickup truck traveling east on 448 below the post speed. I observed a white male driving it, and who quickly turn his face away from me as he pass the work site. I departed the

(b) (6), (b) (7)(C)

site, caught up with the truck. After noting the Mississippi tag # (b) (6), (b) (7) (C) I return to the work site.

On **August 4, 2014** at approximately 12:00 p.m., I received a call from MHP Trooper (b) (6), (b) (7)(C). The purpose of this call was to inform me that he observed (b) (6), (b) (7)(C) driving a black pickup truck near three different locations in an open field. Each of these locations is where BSWA have water mains were present. Trooper (b) (6), (b) (7)(C) observed (b) (6), (b) (7)(C) acting suspiciously outside of his black pickup truck. During one these occasion (b) (6), (b) (7) was observed holding what appeared to be a long T-rod. (T-Rod is used to turn water on and off).

Later the same day, I received a call from (b) (6), (b) (7)(C) via cell phone. (b) (6), (b) (7) advised me that while he was working at a water supply well he observed (b) (6), (b) (7)(C) passing in a black pickup truck. Before departing, I took photos of the area and took possession of a portion of the damaged water line in the event it will be needed for comparison later.

On **Tuesday, August 05, 2014** at approximately 9:49 a.m. (b) (6), (b) (7) (C) contacted me via cell phone. The purpose of this call was to inform me that he had discovered another water line damaged south of Pace.

I responded and arrive a short time at a location approximately 3 miles south Pace on O'Neal Rd. During my observation, I observed water coming from a covered used to conceal the water valve. (b) (6), (b) (7) contained the leak and cleared the water with efforts

(b) (6), (b) (7)(C)

to repair it. From my observation it appeared that someone had used a sharp object to partial cut the water line. There was no other evidence left at the location to make note of.

Before departing, I took photos of the area and took possession of a portion of the damaged water line in the event it will be needed for comparison later.

On Tuesday, **August 19, 2014** at approximately 11:30 p.m., I received a call from (b) (6), (b) (7)(C) of the Boyle Skene Water Association regarding busted water main on Litton Road in Rural Bolivar County. (b) (6), (b) (7) also advised that (b) (6), (b) (7)(C) was close to location when he observed a vehicle traveling from the area of the damage. (b) (6), (b) (7) followed the vehicle to a location south on Shaw Skene Rd near Fly Road. (b) (6), (b) (7) advised that he was able to visually see the Mississippi tag number of (b) (6), (b) (7)(C). It was noted that this vehicle traveled at a high rate of speed as he attempted to identify it.

I responded to the location several miles west of the Litton and Shaw Skene Road intersection. After I arrived, I observed (b) (6), (b) (7)(C) working to repair the damaged pipe that was located on the northwest portion of the bridge. There were no other visible signs of any automobile tire tracks or physical evidence. I photographed the damaged area of the pipe which appeared to have been struck numerous times before it was ruptured.

After departing, I traveled to Fly Road outside of Shaw to attempt to locate the vehicle of interest. However, I was unable to positively identify vehicle parked at and near the local residence due to darkness.

(b) (6), (b) (7)(C)

Open investigation.

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

DRAFT

NO PRIOR REPORTS OF PIPES BEING SHOT OR VANDALIZED.

NO PRIOR SHERIFF'S DEPARTMENT REPORTS EVER MADE.

BOARD MEETING

February 21, 2014 - Board Meeting

1. (b) (6), (b) (7) released from employment.

HITER ROAD

February 25, 2014

1. Pipe in ditch on Hiter Road shot.
2. (b) (6), (b) (7) found 40 cal. shell casings.
3. (b) (6), (b) (7) saw (b) (6), and (b) (6), (b) (7) in (b) (6), (b) (7)(C) truck in vicinity shortly before leak was reported.
4. Pipe is visible from bridge.
5. (b) (6), (b) (7) repaired leak.
6. Incident scene near (b) (6), (b) (7)(C) home.

WATER SAMPLES

February 25, 2014 - Water samples pulled by (b) (6), (b) (7) at follows:

- 1 - Benoit water tower
 - 1 - Skene water tower
 - 2 - Rizzo water tower
 - 2 - East Cleveland water tower
-
1. (b) (6), (b) (7) spoke with (b) (6), (b) (7) on day samples were pulled.
 2. (b) (6), (b) (7) took box, samples and custody seals to Department of Health.
 3. No control of samples at Department of Health.
 4. Could have been switched at Department.
 5. (b) (6), (b) (7) could have adulterated with help from (b) (6), (b) (7) prior to (b) (6), (b) (7) sealing samples.

February 27, 2014

1. All 6 samples tested positive for E coli.
2. Impossible for all 6 samples to test positive.
3. All fed by separate wells.
4. All tested clear next day and next 3 samples pulled.

5. (b) (6), (b) (7)(C) pulled samples on February 27, 2014 within 3 hours of receiving notice of contamination.
6. E coli cannot have been present system wide and vanish within that time frame.

February 27, 2014

1. All 6 samples tested positive for E coli.
2. Impossible for all 6 samples to test positive.
3. All fed by separate wells.
4. All tested clear next day and next 3 samples pulled.
5. (b) (6), (b) (7)(C) pulled samples on February 27, 2014 within 3 hours of receiving notice of contamination.
6. E coli cannot have been present system wide and vanish within that time frame.

LITTON ROAD

March 27, 2014

1. Pipe in ditch busted by concrete rubble lying on ditch bank.
2. Pipe actually under water.
3. Knew it was there.
4. Within 3/4 of a mile from Shaw/Skene Road incident.
5. Same line and between Shaw/Skene Road incident and 4th of July incident.
6. Occurred same day as water operator training class in Jackson.
7. (b) (6), (b) (7) had originally been scheduled to attend.
8. Knew (b) (6), (b) (7) would be out of town when incident occurred.
9. Leak fixed by (b) (6), former employee of Boyle/Skene.
10. (b) (6), (b) (7) stated, "grass on ditch bank was over his head but there was a clear line where someone had walked down to it."
11. (b) (6), (b) (7) did not call Sheriff's Department as instructed and did not take photos as instructed.

LETTER TO (b) (6), (b) (7)(C) CANCELING INSURANCE

May 2, 2014 - Letter to (b) (6), (b) (7) canceling insurance.

WALKER ROAD

May 4, 2014

1. Sheriff's Department called to scene.
2. Line busted in a ditch with blunt instrument.

3. Photos at Sheriff Department's office.
4. Pipe in ditch.
5. Incident actually in Sunflower County.
6. Near (b) (6), (b) (7)(C) home.
7. Disrupted (b) (6), (b) (7)(C) service.
8. Cannot see pipe from any road.
9. Had to know where pipe was.
10. Had to physically descend the ditch bank to get to pipe.
11. 2 days after letter from Boyle/Skene to (b) (6), (b) (7)(C) canceling insurance.

ANNUAL MEETING

May 6, 2014 - Boyle/Skene Annual Meeting

1. Extremely contentious.
2. (b) (6), (b) (7)(C) tries to oust 2 Board Members, (b) (6), (b) (7)(C) and (b) (6), (b) (7)(C).
3. Confrontation with (b) (6), (b) (7)(C).

LETTER FROM (b) (6), (b) (7)(C)

May 19, 2014 - (b) (6), (b) (7)(C) writes letter to Board demanding action and giving Board 10 days to respond.

O'NEAL RAOD

May 28, 2014 - Pipe in field off of O'Neal Road struck with sharp object.

1. (b) (6), (b) (7)(C) repaired leak.
2. No field work had been done on that field.
3. (b) (6), (b) (7)(C) stated "appeared hit with an ax".
4. Pipe actually underground but very shallow, maybe 10"
5. Pipe had been fixed by (b) (6), (b) (7)(C) prior to that incident. He knew it was shallow, knew its exact location, knew it would be very difficult to locate.
6. Incident occurs exactly 10 days after Board received letter from (b) (6), (b) (7)(C) giving Board 10 days to respond.
7. Photos of pipe.

SHAW SKENE ROAD

June 7, 2014 - Pipe shot near Shaw Skene Road

1. First noticed leak at 1:30 p.m.
2. Took 5 hours to find leak.

15. Incident filed with the Sheriff's Department.
16. Photos of pipe.

NEWSPAPER ARTICLE

July 8, 2014

Received draft of newspaper article.

(b) (6),
(b) (7) quoted:

"There's no reason everyone should have been without water."

"There are valves that can be cut off to isolate the problem."

"You could have had only one section of pipe that was off where there was no house on it."

"When I found out people were out of water at Benoit, I contacted people who had cabins and told them what valves to turn off so they could get water back."

Informed by paper staff, (b) (6), (b) (7)(C) that (b) (6), (b) (7)(C) called her and told her we were meeting with FBI, Thursday the 17th.

July 10, 2014

Letter hand delivered to (b) (6), (b) (7)(C) re (b) (6), (b) (7)(C) affair at his place of employment (Faurecia).

Originally investigated (b) (6), (b) (7)

Instructed to reveal findings after client's death.

(b) (6), (b) (7)(C) wife died 2011-2012.

Delivered the week between (b) (6), (b) (7) birthdays.

(b) (6), (b) (7) was the person who took (b) (6), (b) (7) to airport to pick up her vehicle.

July 16, 2014 - (b) (6), (b) (7)(C) receives letter sent to (b) (6), (b) (7)(C)

July 17, 2014 - FBI meeting known by newspaper and (b) (6), (b) (7)(C)

IMPORTANT NOTES

1. No instances of vandalism prior to (b) (6), (b) (7) release.
2. Each act of vandalism occurs immediately before or after some event regarding (b) (6), (b) (7)(C) employment.
3. (b) (6), (b) (7) can be placed near the scene of 2 incidents prior to the vandalism, i.e. 4th of July and Hiter Road.
4. (b) (6), (b) (7) can be placed at the scene of 3 incidents during the repair work, i.e. 4th of July, Litton Road and Shaw Skene Road. No way (b) (6), (b) (7) could have known

- about the Litton Road or Shaw Skene Road incidents.
5. (b) (6), (b) (7)(C) are the 3 main members that pushed for (b) (6), termination.
 6. 4 of the acts of vandalism occurred near the home of all 3 Board members and disrupted water service to (b) (6), (b) (7)(C)
 7. 4th of July incident occurred when it could do most damage.
 8. 4th of July incident occurred in a strategic location where (b) (6), and only (b) (6), would have known it would cause the most damage.
 9. All but the 4th of July and Hiter Road incidents occurred at locations unknown to the general public.
 10. (b) (6), (b) (7) had access to sample boxes, custody seals and sample bottles.
 11. (b) (6), (b) (7)(C) gets copy of package sent to (b) (6), (b) (7) on day before meeting with FBI takes place.
 12. (b) (6), (b) (7) boyfriend gets package one week before meeting takes place.
 13. Statements to newspaper about calls made to Outing Club Members regarding valves can be easily verified by phone records.
 14. May strike again in response to letter I write.

EVIDENCE ON HAND

1. Photos
2. Shell casings
3. Damaged pipe segments
4. Briefcase
5. Ipad

INCIDENT/OFFENSE REPORT

BOLIVAR COUNTY SHERIFF'S OFFICE

INCIDENT NO. 2014060053	RESPONSIBLE AGENCY BOLIVAR COUNTY SHERIFF'S OFFICE	STATUS Open	CALL NO. 2014002666																				
REPORTED INCIDENT/OFFENSE BROKEN WATER LINE		REPORTED DATE 06/07/2014	<input type="checkbox"/> NCIC Check Made <input type="checkbox"/> DUI Offense																				
ACTUAL INCIDENT/OFFENSE MALICIOUS MISCHIEF	OFFENSE CODE 97-3-7(2)	STATUTE CODE 97-3-7(2)	FROM Date/Time 06/07/2014 - 19:27 TO Date/Time 06/07/2014 - 21:21																				
OFFENSE LOCATION/FIRM SHAW SKENE AND LITTON RD		LOC. TYPE 47	DISTRICT 																				
ADDRESS SHAW SKENE AND LITTON		APT. NO. 	CITY 																				
COMPLAINANT (b) (6), (b) (7)(C)		HOME PHONE 	EMPLOYER WORK PHONE 																				
M. O. / E V I D E N C E	WEATHER CONDITIONS		HOW DONE																				
	<input type="checkbox"/> Warm <input type="checkbox"/> Clear <input type="checkbox"/> Raining <input checked="" type="checkbox"/> Cloudy <input type="checkbox"/> Snowing <input type="checkbox"/> Foggy		N/A																				
	STRUCTURE OCCUPANCY Not Applicable		Weapons/Tools Used : N/A Force Used : N/A Other Trademarks : N/A																				
	<input type="checkbox"/> Glove Prints <input type="checkbox"/> Foot Prints <input type="checkbox"/> Stains - Blood <input type="checkbox"/> Stains - Semen <input type="checkbox"/> Stains - Other body fluids <input type="checkbox"/> Tools/Instruments		<input type="checkbox"/> Tool Marks <input type="checkbox"/> Fingerprints <input type="checkbox"/> Tire Tracks <input type="checkbox"/> Photographs <input type="checkbox"/> Insulation/Dust <input type="checkbox"/> Weapon																				
	<input type="checkbox"/> Bullets <input type="checkbox"/> Paint Samples <input type="checkbox"/> Hair <input type="checkbox"/> Glass Fragments <input type="checkbox"/> Documents <input type="checkbox"/> Mud/Soil		<input type="checkbox"/> Cigarette Butts <input type="checkbox"/> Drugs/Paraphernalia <input type="checkbox"/> Clothing <input type="checkbox"/> Vehicle(s) <input type="checkbox"/> Other _____ Desc:																				
EVIDENCE GATHERED NO EVIDENCE GATHERED																							
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;">HOW INVOLVED</th> <th style="width: 35%;">NAME</th> <th style="width: 35%;">ADDRESS</th> <th style="width: 15%;">PHONE NO.</th> </tr> </thead> <tbody> <tr> <td>Complainant</td> <td>(b) (6), (b) (7)(C)</td> <td>(b) (6), (b) (7)(C)</td> <td></td> </tr> <tr> <td>Suspect Person</td> <td>(b) (6), (b) (7)(C)</td> <td>(b) (6), (b) (7)(C)</td> <td></td> </tr> <tr> <td>Witness</td> <td>(b) (6), (b) (7)(C)</td> <td>(b) (6), (b) (7)(C)</td> <td>(b) (6), (b) (7)(C)</td> </tr> <tr> <td>Witness</td> <td>(b) (6), (b) (7)(C)</td> <td>(b) (6), (b) (7)(C)</td> <td>(b) (6), (b) (7)(C)</td> </tr> </tbody> </table>				HOW INVOLVED	NAME	ADDRESS	PHONE NO.	Complainant	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)		Suspect Person	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)		Witness	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)	Witness	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)
HOW INVOLVED	NAME	ADDRESS	PHONE NO.																				
Complainant	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)																					
Suspect Person	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)																					
Witness	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)																				
Witness	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)																				
DISPOSITION OF PROPERTY :			TOTAL VALUE : \$ 0.00																				
Officer(s) Involved : Primary-SO24 (b) (6), (b) (7)(C) Special-SO7 (b) (6), (b) (7)(C)																							
Investigator Assigned : SO7 (b) (6), (b) (7)(C) Investigative Div. : PATROL/CID																							
CASE FILED Yes <input checked="" type="checkbox"/>																							
THIS CASE IS Cleared by Arrest <input type="checkbox"/> Unfounded <input type="checkbox"/> Exceptionally Cleared <input type="checkbox"/> Other <input checked="" type="checkbox"/>																							
APPROVED BY																							

INCIDENT REPORT - NARRATIVE

BOLIVAR COUNTY SHERIFF'S OFFICE

INCIDENT NO. 2014060053	INCIDENT DATE/TIME 06/07/2014/19:27	MALICIOUS MISCHIEF
-------------------------	-------------------------------------	--------------------

7 June 14 On this date I, Deputy (b) (6), was dispatched to the intersection of Shaw Skeen Rd and Litton Rd in Skeen MS Bolivar County to meet a complainant about a broken waterline. Upon my arrival I spoke with complainant, (b) (6), (b) (7)(C) and he advised that someone had shot a four inch water main causing it to break. This four inch water main is owned and maintained by Boyle Skeen Water Association. The break in this line also caused customer outages.

(b) (6), (b) went on to say that they believe the suspect to be (b) (6), (b) (b) was seen in the area not far from the broken water line when it was located. (b) (6), (b) used to be employed by Boyle Skeen Water Association but was terminated. Since his termination there have been multiple issues with pipes being shot and broken by other means. (b) (6) was in charge of servicing all the water lines so he has intimate knowledge of where all the lines are. The line that was broken today was in the bottom of a ditch that had to be accessed by turning off the road on Litten Rd and following the edge of a field around to it.

(b) (6), goes on to say that they were notified of the outage at about two o'clock this date. They went out looking for where the break could be. (b) (6), (b) of Phillips Plumbing was on Shaw Skeen Rd when he saw (b) (6), (b) (7)(C) an employee of Phillips Plumbing, also saw (b) and tried to stop him. At first (b) would not stop but he later did. (b) asked him where the turn off valve for the area was and (b) told him down toward (b) (6), (b) (7)(C). The actual location of the turn off valve for the area was back on Shaw Skeen Rd. (b) (6), actually found the break by riding the edge of the field.

I collected the information for this report and called for a an investigator to come to the scene. Investigator (b) (6), (b) came to the scene and questioned the witnesses. We were told that (b) lives in the Interstate Community (b) (6), (b) (7)(C). (b) (6), (b) . Myself and Investigator (b) went to this location but was unable to locate (b) (6), investigation turned over to CID.EOR

OFFICER'S SIGNATURE : _____

INCIDENT/OFFENSE REPORT

BOLIVAR COUNTY SHERIFF'S OFFICE

INCIDENT NO. 2014090006		RESPONSIBLE AGENCY BOLIVAR COUNTY SHERIFF'S OFFICE		STATUS Open		CALL NO. 2014004022		
REPORTED INCIDENT/OFFENSE WATER LINE SHOT				REPORTED DATE 09/02/2014		<input type="checkbox"/> NCIC Check Made <input type="checkbox"/> DUI Offense		
ACTUAL INCIDENT/OFFENSE MALICIOUS MISCHIEF/VANDALISM		OFFENSE CODE 63-3-403		STATUTE CODE 63-3-403		FROM Date/Time 09/02/2014 - 16:36		
				TO Date/Time 09/02/2014 - 17:33				
OFFENSE LOCATION/FIRM FRAISER RD				LOC. TYPE 79		DISTRICT SECOND JUDICIAL		
				GRID 1				
ADDRESS 0000 FRAISER RD		APT. NO.		CITY CLEVELAND, MS				
COMPLAINANT (b) (6), (b) (7)(C)		HOME PHONE (b) (6), (b) (7)(C)		EMPLOYER BOYLE SKENE WATER ASS. 803 N CHRISTMAN - CLEVELAND, MS 38732-		WORK PHONE -		
M. O. / E V I D E N C E	WEATHER CONDITIONS Hot <input type="checkbox"/> Clear <input type="checkbox"/> Raining <input type="checkbox"/> Cloudy <input checked="" type="checkbox"/> Snowing <input type="checkbox"/> Foggy <input type="checkbox"/>		HOW DONE SUSPECT USING A FIREARM SHOT TWO HOLES IN A WATER SUPPLY LINE OWNED BY SHAW SKENE WATER ASS					
	STRUCTURE OCCUPANCY Not Applicable		Weapons/Tools Used : Other Force Used : N/A Other Trademarks : N/A					
	<input type="checkbox"/> Glove Prints <input type="checkbox"/> Foot Prints <input type="checkbox"/> Stains - Blood <input type="checkbox"/> Stains - Semen <input type="checkbox"/> Stains - Other body fluids <input type="checkbox"/> Tools/Instruments		<input type="checkbox"/> Tool Marks <input type="checkbox"/> Fingerprints <input type="checkbox"/> Tire Tracks <input type="checkbox"/> Photographs <input type="checkbox"/> Insulation/Dust <input type="checkbox"/> Weapon		<input type="checkbox"/> Bullets <input type="checkbox"/> Paint Samples <input type="checkbox"/> Hair <input type="checkbox"/> Glass Fragments <input type="checkbox"/> Documents <input type="checkbox"/> Mud/Soil		<input type="checkbox"/> Cigarette Butts <input type="checkbox"/> Drugs/Paraphernalia <input type="checkbox"/> Clothing <input type="checkbox"/> Vehicle(s) <input checked="" type="checkbox"/> Other _____ Desc: COMPLAINANT TESTIMONEY	
	EVIDENCE GATHERED		NO EVIDENCE GATHERED					
HOW INVOLVED Complainant		INVOLVED PERSON(S) NAME (b) (6), (b) (7)(C) ADDRESS PHONE NO.						
DISPOSITION OF PROPERTY :						TOTAL VALUE : \$ 0.00		
Officer(s) Involved : Primary-24 (b) (6), (b) (7)(C) OFFICER (b) (6), (b) (7)(C)								
Investigator Assigned : 24 (b) (6), (b) (7)(C) OFFICER (b) (6), (b) (7)(C) Investigative Div. : PATROL								
CASE FILED Yes <input checked="" type="checkbox"/>		THIS CASE IS Cleared by Arrest <input type="checkbox"/> Unfounded <input type="checkbox"/> Exceptionally Cleared <input type="checkbox"/>		Other <input checked="" type="checkbox"/>		APPROVED BY		

INCIDENT REPORT - NARRATIVE

BOLIVAR COUNTY SHERIFF'S OFFICE

INCIDENT NO. 2014090006

INCIDENT DATE/TIME 09/02/2014/16:36

MALICIOUS MISCHIEF/VANDALISM

2SEPT14 On this date I, Deputy (b) (6), was dispatched to White St in Cleveland MS Bolivar County to take a report of malicious mischief. Upon arrival I spoke with complainant, (b) (6), (b) (7) and he advised me that another water supply line had been shot. I was walked over to the area where the line crossed the ditch and observed two holes in the pipe leaking water. These holes are consistent with being shot.

The water lines are owned by Boyle Skene Water Ass. and alot of these lines around the county have been shot and busted over the last several months. All these occurances started after the Water Ass. fired an employee and this person is suspected of all the crimes.

At the time of this call it was discovered that another line had also been shot on Fraiser Rd also. It is suspected that the same perpetrator also committed this crime.

OFFICER'S SIGNATURE : _____

INCIDENT/OFFENSE REPORT

BOLIVAR COUNTY SHERIFF'S OFFICE

INCIDENT NO. 2014090042	RESPONSIBLE AGENCY BOLIVAR COUNTY SHERIFF'S OFFICE	STATUS Open	CALL NO. 2014004152
REPORTED INCIDENT/OFFENSE SHOT WATER LINE		REPORTED DATE 09/10/2014	<input type="checkbox"/> NCIC Check Made <input type="checkbox"/> DUI Offense
ACTUAL INCIDENT/OFFENSE MALICIOUS MISCHIEF		OFFENSE CODE	STATUTE CODE
OFFENSE LOCATION/FIRM 0000 ODOM ROAD WEST CLEVELAND, MS		FROM Date/Time 09/10/2014 - 17:39	TO Date/Time 09/10/2014 - 18:48
ADDRESS 0000 ODOM ROAD		APT. NO.	CITY CLEVELAND, MS
COMPLAINANT (b) (6), (b) (7)(C)		HOME PHONE	EMPLOYER BOYLE SKENE WATER ASS. 803 N CHRISTMAN - CLEVELAND, MS 38732-
WEATHER CONDITIONS		HOW DONE	
<input type="checkbox"/> Hot <input type="checkbox"/> Clear <input type="checkbox"/> Raining <input type="checkbox"/> Cloudy <input type="checkbox"/> Snowing <input type="checkbox"/> Foggy		perpetrator has a knowlege of the water piping system and is randomly shooting supply lines in areas where special knowledge of the piping system is.	
STRUCTURE OCCUPANCY Not Applicable		Weapons/Tools Used : Not Applicable Force Used : FIREARM Other Trademarks : N/A	
<input type="checkbox"/> Glove Prints <input checked="" type="checkbox"/> Foot Prints <input type="checkbox"/> Stains - Blood <input type="checkbox"/> Stains - Semen <input type="checkbox"/> Stains - Other body fluids <input type="checkbox"/> Tools/Instruments		<input type="checkbox"/> Tool Marks <input type="checkbox"/> Fingerprints <input checked="" type="checkbox"/> Tire Tracks <input type="checkbox"/> Photographs <input type="checkbox"/> Insulation/Dust <input type="checkbox"/> Weapon	<input type="checkbox"/> Bullets <input type="checkbox"/> Paint Samples <input type="checkbox"/> Hair <input type="checkbox"/> Glass Fragments <input type="checkbox"/> Documents <input type="checkbox"/> Mud/Soil Desc:
<input type="checkbox"/> Cigarette Butts <input type="checkbox"/> Drugs/Paraphernalia <input type="checkbox"/> Clothing <input type="checkbox"/> Vehicle(s) <input type="checkbox"/> Other			
EVIDENCE GATHERED NO EVIDENCE GATHERED			
HOW INVOLVED Complainant (b) (6), (b) (7)(C)			
INVOLVED PERSON(S) NAME ADDRESS PHONE NO.			
DISPOSITION OF PROPERTY : TOTAL VALUE : \$ 0.00			
Officer(s) Involved : Primary-24 (b) (6), (b) (7)(C) OFFICER (b) (6), (b) (7)(C)			
Investigator Assigned : 24 (b) (6), OFFICER (b) (6) Investigative Div. : PATROL			
CASE FILED		THIS CASE IS	
Yes <input checked="" type="checkbox"/>		Other <input checked="" type="checkbox"/> Cleared by Arrest <input type="checkbox"/> Unfounded <input type="checkbox"/> Exceptionally Cleared <input type="checkbox"/>	
APPROVED BY			

INCIDENT REPORT - NARRATIVE

BOLIVAR COUNTY SHERIFF'S OFFICE

INCIDENT NO. 2014090042

INCIDENT DATE/TIME 09/10/2014/17:39

MALICIOUS MISCHIEF

10Sept14 On this date I, Deputy (b) (6), was dispatched to a location off Odom Rd in Cleveland MS Bolivar County for a report of malicious mischief. Upon my arrival I spoke with the complainant, (b) (6), (b) (7) and he advised that yet again another water supply line had been shot. The water supply line belongs to Boyle Skene Water Utility Company. This line was located West across a field on Odom Rd. This is the third line this month to be shot. It is suspected that a former employee that has the knowledge of the complete water piping system. All these vandalisms started just after this employee was fired from the company.EOR

OFFICER'S SIGNATURE : _____

CALLS FOR SERVICE - CALL INFORMATION SHEET

BOLIVAR COUNTY SHERIFF'S OFFICE

CALL FOR SERVICE INFORMATION

CALL NUMBER 2014004152	REPORTED DATE/TIME 09/10/2014 - 17:39:09	DISPATCHER D-3 (b) (6), (b) (7)(C)	INCIDENT NUMBER 2014090042
REPORTED INCIDENT SHOT WATER LINE (BOYLE SKENE WATER)		HOW CALL WAS RECEIVED Phone Call	
LOCATION (b) (6), (b) (7)(C)			
ADDRESS (b) (6), (b) (7)(C)		CITY CLEVELAND, MS	
TIME RECEIVED 17:39:09	TIME DISPATCHED 17:55:32	TIME 1ST UNIT ARRIVED 18:21:17	TIME CLEARED 18:48:05
<input type="checkbox"/> Fire Fighters Dispatched <input type="checkbox"/> Hazardous Material(s) Involved <input type="checkbox"/> Call was dangerous to Officers <input type="checkbox"/> Ambulance Dispatched <input type="checkbox"/> Hold from Press <input type="checkbox"/> Wrecker Dispatched <input type="checkbox"/> Arrest(s) Made during this call			

CALLER INFORMATION

CALLER'S NAME (b) (6), (b) (7)(C)	FILE NUMBER
ADDRESS (b) (6), (b) (7)(C)	CITY CLEVELAND, MS
PHONE NUMBER (b) (6), (b) (7)(C)	

COMMENTS NOTED

CALLER ADVISED OF A SHOT WATER LINE AT ABOVE LOC. CALLER ADVISED SHE WORKED WITH SHAW SKENE WATER DEPT AND NEEDED DEPUTY FOR REPORT. SO-24 (b) (6), RESPONDED. SO-24 MADE CONTACT WITH COMPL, REPORT TAKEN, BACK IN SERVICE.

**** 09/10/2014 - 19:23:41 ****

UNIT(S) ASSIGNED

Agency	Unit	Dispatch Time	Arrival Time	Time Cleared
BCSO	SO-24	17:55:32	18:21:17	18:48:05